IN THE UNITED STATES DISTRICT COURT FOR THE SOUTHERN DISTRICT OF TEXAS BROWNSVILLE DIVISION

JUAN M. GONZALEZ,	§	
Plaintiff,	§	
	§	
vs.	§	
	§	CASE NO.
STATE FARM LLOYDS,	§	
Defendant.	§	
	§	

EXHIBIT 1

Plaintiff's Pre-Suit Demand and Estimate



2510 S. Veterans Blvd. Edinburg, Texas 78539 Phone: 956.992-8721 * Facsimile: 956.686.0050

March 29, 2016

State Farm PO BOX 106169 Atlanta, GA 30348-619 Via CMRR: 7015.3010.0000.3107.9685,

Attn: Gilbert Santos

Our Clients Policy No. Juan M Gonzalez

.

83BYA7981 53609M126

Claim No. Property

1904 Taxco Dr. Brownsville, TX 78521

D. O. L. : May 28, 2014

DEMAND FOR RELIEF UNDER THE TEXAS DECEPTIVE TRADE PRACTICES-CONSUMER PROTECTION ACT AND THE TEXAS INSURANCE CODE.

Dear Gilbert Santos:

This firm has been retained by **Juan M Gonzalez** to represent him in the handling and prosecution of him claims against **State Farm** under the Texas Deceptive Trade Practices-Consumer Protection Act (DTPA) and under the Texas Insurance Code, section 541.

State Farm is a "consumer(s)" within the definition as set forth in the DTPA because he purchased a policy of insurance from State Farm. It was represented to our client that this policy of insurance was in full force and effect for the policy period, and that any and all claims made by the insured would be handled in a manner consistent with the guidelines set forth in the Texas Insurance Code. In addition, my client is also a "person(s)" under the Texas Insurance Code with standing to bring claims under the Texas Insurance Code.

As you know, the insured has made a claim under the policy of insurance sold to them by State Farm. Your company has conducted an inadequate examination of the damage from the May 28, 2014 hailstorm and the claims made by your insured. To date, the handling of the claims for windstorm/hailstorm and water damage, have resulted in significant problems for my client.

DTPA

The DTPA violations of State Farm include but not limited to:

 Causing confusion or misunderstanding as to the course, sponsorship, approval, or certification of goods or services;

04042016

E-mail: Isabel@livesaylawfirm.com



2510 S. Veterans Blvd. Edinburg, Texas 78539

Phone: 956.992-8721 * Facsimile: 956.686.0050

- Representing that an agreement confers or involves rights, remedies, or obligations, which it does not have or involve, or which are prohibited by law;
- Failure to disclose information concerning goods or services which was known at the time of transaction
 if such failure to disclose such information was intended to induce the consumer into a transaction into
 which the consumer would not have entered had the information been disclosed:
- Misrepresenting to a claimant a material fact or policy provision relating to coverage at issue;
- Failing to attempt in good faith to effectuate a prompt, fair, and equitable settlement of a claim with respect to which the insurers' liability has become reasonably clear;
- 6. Failing to attempt, in good faith, to effectuate a prompt, fair, and equitable settlement under one portion of a policy of a claim with respect to which the insurers' liability has become reasonably clear in order to influence the claimant to settle an additional claim under another portion of the coverage, provided that this prohibition does not apply if payment under one portion of the coverage constitutes evidence of liability under another portion of the policy;
- Failing to provide promptly to a policyholder a reasonable explanation of the basis in the policy, in relation
 to the facts or applicable law, for the insurer's denial of a claim or for the offer of a compromise settlement
 of a claim;
- Failing with a reasonable time to affirm or deny coverage of a claim to a policyholder and/or submit a reservation of rights to a policyholder;
- Refusing, fulling, or unreasonably delaying an offer of settlement under applicable first party coverage on the basis that other coverage may be available or that third parties are responsible for the damages suffered, except as may be specifically provided in the policy;
- 10. Undertaking to enforce a full and final release of a claim from a policyholder when only a partial payment has been made, provided that this prohibition does not apply to a compromise settlement of a doubtful or disputed claim;
- 11. Refusing to pay a claim without conducting a reasonable investigation with respect to the claim;
- 12. Making an untrue statement of material fact;
- Failing to state a material fact that is necessary to make other statements made not misleading; considering the circumstances under which the statements were made;
- Making a statement in such manner as to mislead a reasonably prudent person to a false conclusion of a material fact
- 15. Making a material misstatement of law; and
- Failing to disclose any matter required by law to be disclosed, including a failure to make disclosure in accordance with another provision of the Texas Insurance Code.

State Farm actions are in violation of the DTPA and constitute producing causes of damage to my client.

Because of the nature of the claims and the circumstances surrounding the losses in question, State Farm decision to deny the claims or to delay payment on the claims even though it is reasonably clear the claims are covered constitutes "knowing" violations of the DTPA and the Texas Insurance Code sufficient to allow the imposition of



2510 S. Veterans Blvd. Edinburg, Texas 78539 Phone: 956.992-8721 * Facsimile: 956.686.0050

treble damages. Moreover, State Farm' "knowing" violations of the Texas Insurance Code and the DTPA have caused and continue to cause significant mental anguish to my client.

Furthermore, because of your State Farm violations of the DTPA and the Texas Insurance Code, our client is entitled to recover attorney's fees.

Texas Insurance Code Violations

State Farm and its representatives have violated the Texas Insurance Code in the following manner including, but are not limited to:

- Refusing to pay a claim without conducting a reasonable investigation with respect to the claim;
- Making an untrue statement of material fact;
- Failing to state a material fact that is necessary to make other statements made not misleading, considering the circumstances under which the statements were made;
- Making a statement in such manner as to mislead a reasonably prudent person to a false conclusion
 of a material fact;
- 5. Making a material misstatement of law, or
- Failing to disclose any matter required by law to be disclosed, including a failure to make disclosure in accordance with another provision of the Texas Insurance Code.

*Breach of Duty of Good Faith and Fair Dealing: Bad Faith *

In addition, State Farm violated the duty of good faith and fair dealing by refusing to pay the claims in question even though you and your company knew or should have known that it was reasonably clear the claims were covered. State Farm's breach of its duty of good faith and fair dealing has proximately caused injury and damage to my client.

*Breach of Contract *

Moreover, by failing to pay benefits under the policy of insurance, **State Farm** breached the contract of insurance that existed between your company and our client. As a result, our client is entitled to recover actual damages, consequential damages and attorney's fees pursuant to §38.001 of the Texas Civil Practice & Remedies Code because of your breach of contract.

At this time, my client has to face the reality of not being able to live in her home while repair of the premises takes place in order to reduce or eliminate the very real dangers presented by the damages to the property. The potential costs of fixing the problems with the house are staggering, and that is why our client turned to you, their insurance representative and company, for assistance in this time of dire need. However, instead of help or adequate assistance, my client has suffered significant and real harm because of your misguided decisions.

04042016



2510 S. Veterans Blvd. Edinburg, Texas 78539

Phone: 956.992-8721 * Facsimile: 956.686.0050

As a result, please allow this correspondence to constitute notice under the Texas Deceptive Trade Practices Act and under the Texas Insurance Code of the claim, against you and your representatives. Please allow this correspondence to serve as notice pursuant to Chapter 38,001 of the Texas Civil Practice & Remedies Code.

The damages suffered by our client to date include:

Total All Economic Damages : \$ 26,902.37 (Scope attached as Exhibit A)

Prior Payment : -\$ 0.00 Attorney Fees : \$ 8,877.78 TOTAL : \$ 35,780.15

Because of the nature of the claims and the circumstances surrounding the losses in question, State Farm's actions constitute "knowing" violations of the DTPA and the Texas Insurance Code sufficient to allow the imposition of treble damages up to 3 times economic damages. Please let this letter serve as my client's demand for a total of \$35,780.15.

Sincerely, The Law Offices of R. Kent Livesay, PC

R. Kent Livesay Attorney at Law

المنسور إماليو الاناور

EXHIBIT

A

84942918

Stone ate Stonegate Construction & Restoration, LLC

5303 N McColl McAllen, TX 78504 956- 992-8747

Insured

Gonzalez, Juan

Property

1904 Taxen Dr

Brownsville, TX 78521

Claim Rep.,

Randy Crow

Estimator

Randy Crow

Claim Number:

Policy Number: 83-BY-A798-1

Type of Loss: Wind/Hail Damage

Date Contacted:

2/19/2015

Date of Loss:

5/28/2014

Date Received

2/19/2015

Date Inspected: 2/19/2015

Date Entered 2/19/2015 3:34 PM

Price List: TXMC8X_FEB15

Restoration/Service/Remodel

Estimate: 2015-02-19-1534

Stone ate Stonegate Construction & Restoration, LLC

5303 N. McColl McAllen, TX 78504 956- 992-8747

2015-02-19-1534 SKETCH1 Main Level

Roof1

DESCRIPTION		QTY	UNIT PRICE	TOTAL
R&R Ridge cap - composition shingles	216.34	LF@	4.76 =	1,029.78
Remove Tear off, haul and dispose of comp. shingles - Laminated		SQ@	49.39 =	1,012.99
 Laminated - comp. shingle rfg w/out felt 		so @	161.72 =	3,827.91
4. Roofing felt	23.59	SQ@	23.40 =	552.01
 Asphalt starter - universal starter course 		LF@	1.26 =	290.06
6. R&R Drip edge		LF@	1.65 =	379.84
7. Seal & paint trim - two coats		LF@	0.93 =	214.10
8. R&R Valley metal		LF@	3.86 =	274.95
9. R&R Roof vent - turtle type - Metal		EA@	43.19 =	86.38
 R&R Flashing - pipe jack 	5.00	EA@	27.98 =	139.90
11. Prime & paint roof jack	5.00	EA@	23.78 =	118.90
 Digital satellite system - Detach & reset 	1.00	EA@	22.30 =	22,30
 Digital satellite system - alignment and calibration only 	1.00	EA@	66.89 =	66.89
14. General clean - up		HR@	26.66 =	213.28

Right Elevation

Windows

DESCRIPTION	QTY	UNIT PRICE	TOTAL
15. Reglaze double-pane thermal window unit	1.00 EA@	226.23 =	226.23
16. R&R Window screen	1.00 EA@	26.26 =	26.26
17. General clean - up	1.00 HR @	26.66 =	26.66

Left Elevation

Windows

QTY	UNIT PRICE	TOTAL
1.00 EA@	226.23 =	226.23
1.00 EA @	26.26 =	26.26
1.00 HR @	26.66 =	26.66
	1.00 EA@ 1.00 EA@	1.00 EA @ 226.23 = 1.00 EA @ 26.26 =

Stonegate Construction & Restoration, LLC

5303 N. McColl McAllen, TX 78504 956- 992-8747

SKETCH2 Interior

Living Room					Height: Tray
fissing Wall 14' X 8'		O	pens into		
DESCRIPTION			QTY	UNIT PRICE	TOTAL
Celling					<u> </u>
21. Chandelier - Detach & reset		1.00	EA @	84.04 =	84.04
22. Detach & Reset Heat/AC register		1.00	EA @	8 80 =	8.80
23. R&R Blown-in insulation		242,51	SF @	1.18 =	286.16
24 R&R Drywall - hung, taped, ready for texture		242.51	SF @	1.56 =	378.32
25. Apply anti-microbial agent		242.51	SF@	0.16 ₽	38.80
26. Seal the ceiling w/PVA primer		242:51	SF@	0.39 =	94.58
27. Texture drywall - machine		242.51	SF @	0:31 =	75.18
28. Paint the ceiling - two coats		242.51	SF@	0.65 =	157,63
Walls					
29. Detach & Reset Window dropery - hardware		1.00	LA @	22:40 == 1	22.40
30. Paint the walls		368.00	SF @	0.64 ≈	235:52
Clean/Mask/Move/Protect/Scaffolding					
31. Contents - move out then reser		1.00	EAGO	53,46 =	53.46
32. Musk perimeter of ceiling.		46.00	LITE	0.28 =	45:08
33. Mask the walls of walls		368.00	SF/@	0.17 =	62.56
34 Mask perimeter of floor		46,60	LF (a)	(1;9 8 =	45.03
35. Floor protection -cloth - skid resistant: leak pr	øof	222.83	Siva	0. 72 .=	160,44
16. Final cleaning construction - Residential		222.83	SF@	0.47 =	37.88

Dining Room					Height: Trny	
Missing Wall Missing Wall	•-		Opens into LIVING_ROOM			
ESCRIPTION		Opens into KITCHEN OTY UNIT PRICE			TOTAL	
Ceiling		<u> </u>	· · ·			
37 Chandelier - Detach & reset		1.00	EA @	84 04 =	84.04	
38 Detach & Reset Heat/AC regist	er	1.00	EA @	8 80 =	8.80	
39 R&R Blown-in insulation		167 67	SF @	118=	197.85	
40 R&R Drywall - hung, taped, rea	idy for texture	167 67	SF @	1 56 =	261.57	
41 Apply anti-microbial agent		167 67	SF @	0 16 =	26.83	
42 Seal the ceiling w/PVA primer		167 67	SF @	0.39 =	65 39	
43 Texture drywall - machine		167 67	SF @	0.31 =	51 98	
44 Paint the ceiling - two coats		167 67	SF (a)	0 65 =	108.99	
Walls						
015-02-19-1534				2/19/2015	Page:	

Stone atc Stonegate Construction & Restoration, LLC

5303 N. McColl McAllen, TX 78504 956-992-8747

CONTINUED - Dining Room

DESCRIPTION		QTY	UNIT PRICE	TOTAL
45. Detach & Reset Window drapery - hardware	1.00	EA@	22.40 =	22.40
46. Paint the walls	199.33	SF@	0.64 =	127.57
Clean/Mask/Move/Protect/Scaffolding				
47. Contents - move out then reset	1.00	EA@	53.46 =	53.46
48. Mask perimeter of ceiling	24.92	LF@	0.98 =	24.42
49. Mask the walls of walls	199.33	SF@	0.17 =	33.89
50. Mask perimeter of floor	24.92	LF@	0.98 =	24.42
51. Floor protection - cloth - skid resistant, leak proof	152.28		0.72 =	109.64
52. Final cleaning - construction - Residential	152,28	SF@	0.17 =	25.89

Kitchen					Height: 8'
Missing Wali 10' 7" X 8'		'all 10' 7" X 8' Opens into DIN			
DESCRIPTION			QTY	UNIT PRICE	TOTAL
Ceiling					
53. Detach & Reset Light fixture		1.00	EA@	32.32 =	32.32
54. Detach & Reset Heat/AC regist	er	1.00	EA@	8.80 =	8.80
55. R&R Blown-in insulation		112.89	SF@	1.18 =	133.21
56. R&R Drywall - hung, taped, rea	dy for texture	112.89	SF@	1.56 =	176.11
57. Apply anti-microbial agent		112.89	SF@	0.16=	18.06
58. Seal the ceiling w/PVA primer		112.89	SF@	0.39 ==	44.03
59. Texture drywall - machine		112.89	SF@	0.31 =	35.00
60. Paint the ceiling		112.89	SF@	0.64 =	72.25
Walls					
61. Detach & Reset Window draper	ry - hardware	1.00	EA@	22.40 =	22.40
62. Detach & Reset Custom cabinet	ts - wall units	21.00	LF@	30.19 =	633.99
63. Stain & finish cabinetry - upper	- inside and out	21.00	LF@	32.50 =	682.50
64. Stain & finish cabinetry - lower	- inside and out	16.00	LF@	38.15 =	610.40
65 Seal & paint casing		15.83	LF@	1.37 =	21.69
66. Seal & paint baseboard		13.08	LF@	1.37 =	17.92
67. Paint the walls		256.67	SF@	0.64 =	164.27
Clean/Mask/Move/Protect/Scaffol	ding				
68. Detach & Reset Refrigerator		1.00	EA@	25.79 =	25.79
69. Detach & Reset Range - freesta	nding - gas	1.00	EA@	111.82 =	111.82
15-02-19-1534				2/19/2015	Page Page

Stonegate Construction & Restoration, LLC

5303 N McColl McAtten, TX 78504 956- 992-8747

CONTINUED - Kitchen

DESCRIPTION		QTY	UNIT PRICE	TOTAL
70 Detach & Reset Range hood	1.00 E	A @	55.47 =	55.47
71. Contents - move out then reset	1,00 E.	A @	53.46 =	53 46
72. Mask perimeter of ceiling	32.08 L	F W	0.98 =	31.44
73. Mask the walls of walls	256.67 S	4.	0.17 =	43.63
74. Mask perimeter of floor	32.08 1	****	0 98 =	31.44
75. Floor protection - cloth - skid resistant, leak proof	112.89 S	_	0.72 =	81.28
76. Final cleaning - construction - Residential	112.89 S	iF @	0.17=	19.19

Bathroom				Height: 8*
DESCRIPTION		QTY:	UNIT PRICE	IOTAL.
Ceiling			 .	
77. Exhaust fan - Detach & reset	1.00	EA(a)	116.71 =	116.71
78 Detach & Reser Heat/AC register	1.00	EAGO	8.80 ~	8 89
79 R&R Blown-in insulation	41 72	SF @	1:18'⇔:	49.23
80/ R&R Drywall - hung, taped, ready for texture	41.72	SF@	1.56 ≔	65.02
81. Apply anti-microbial agent	44.72	8F@	0.16 =	6.68
82. Seal the ceiling:w/PVA primer	41.72	SF/@	0.39=	16.27
83. Texture drywall - machine	41 72	SF @	0.31 ≈	12.93
84 Paint the ceifing	41.72	SF @	0.64 =	26.70
Walls				
85 Detach & Reset Toilet	3 00	EA @	170 28 =	170.28
86. Detach & Reset Mirror	1.00	SF @	4.02 =	4.02
87 Detach & Reset Light bar	1.00	EA (a)	32.00 =	32.00
88. Detach & Reset Shower curtain rod	1 00	EA @	10 46 =	10.46
89 Seal & paint casing	15.83	LF 🔞	1 37 =	21 69
90 Scal & paint baseboard	26.75	LF \bar{a}	1.37 =	36.65
91 Paint the walls	214.02	SF @	0 64 =	136.97
Clean/Mask/Move/Protect/Scaffolding				
92. Contents - move out then reset	1.00	EA Æ	53 46 =	53 46
93. Mask perimeter of ceiling	26 75	LF @	0.98 =	26.22
94 Mask the walls of walls	214 02	SF @	017≖	36.38
95 Mask perimeter of floor	26.75	LF @	0.98 ==	26.22
96 Floor protection - cloth - skild resistant, leak proof	41.72	SF 🛍	0 72 =	30.04
97. Final cleaning - construction - Residential	41 72	SF @	0 17 =	7 09
2015-02-19-1534			2/19/2015	Page: 5

Stone ate Stonegate Construction & Restoration, LLC

5303 N. McColl McAllen, TX 78504 956- 992-8747

CONTINUED - Bathroom

	QTY	UNIT PRICE	TOTA
General Requi	rements		
DESCRIPTION	OTEN	FORTE POYOR	ten ettiden a
	QTY	UNIT PRICE	TOTA
98. Moving van (24' - 27') and equipment - per day	2.00 EA @	163.59 =	327.1
 Inventory, Packing, Boxing, and Moving charge - per hour Off-site storage & insur climate controlled - per month 	30.00 HR @ 500.00 SF @	26.13 = 0.89 =	783.9 445.0
P. L. /- D			
Debris Removal			
DESCRIPTION	QTY	UNIT PRICE	TOTA
	QTY 2.00 EA@	UNIT PRICE 589.34 =	TOTA 1,178.6
DESCRIPTION		37.710.33.34	
DESCRIPTION 101. Dumpster load		37.710.33.34	1,178.6
DESCRIPTION 101. Dumpster load On - Site Sanitation	2.00 EA @	589.34 =	1,178.6 TOTA
DESCRIPTION 101. Dumpster load On - Site Sanitation DESCRIPTION 102. Temporary toilet (per month)	2.00 EA @	589.34 =	1,178.6 TOTA
DESCRIPTION 101. Dumpster load On - Site Sanitation DESCRIPTION	2.00 EA @	589.34 =	

Taxes, Insurance, and Permits

2015-02-19-1534

2/19/2015 @ 42 @ Page: 6

Stone ate Stonegate Construction & Restoration, LLC

5303 N. McColl McAllen, TX 78504 956- 992-8747

DESCRIPTION	QTY	UNIT PRICE	TOTAL
104. Taxes, insurance, permits & fees	1.00 EA@	750.00 =	750.00

Labor Minimums Applied

DESCRIPTION	QTY	UNIT PRICE	TOTAL
105. Window labor minimum	1.00 EA @	16.93 =	16.93
106. Heat, vent, & air cond. labor minimum	1.00 EA @	132.44 =	132.44
107. Water extract/remediation labor minimum	1.00 EA@	13.69 ==	13.69
108: Window treatment repair	1.00 EA @	34.99 =	34.99
109. Mirror/shower door labor minimum	1.00 EA @	98.21 =	98.21
1103 Finish hardware labor minimum	1.00 EA@;	91.77 =	91.77

Grand Total Areas:

1,038.02	SF Walls	564/79	SF Ceiling	1,602.81 SF Walls and Ceiling
529.72	SF Floor	58.86	SY Flooring	129.75 LF Floor Perimeter
0.00	SF Long Wall	0.00	SF Short Wall	129,75 LF Ceil: Perimeter
529.72	Floor Area:	573(84)	Total Area	1,038.02 Interior Wall Area
1,215.77	Exterior Wall Area	135:09.	Exterior Perimeter of Walls	
151.79	Surface Area:	1.52	Number of Squares	96.00 Total Perimeter Length
0.00	Total Ridge Length	34.87	Total Hip Length	- ,

2015-02-19-1534 2/19/2015 Page: 7

Stone atc Stonegate Construction & Restoration, LLC

5303 N. McColl McAllen, TX 78504 956- 992-8747

Summary for Dwelling

Line Item Total Material Sales Tax Cleaning Mtl Tax	21,837.81 414,35 0.95
Subtotal Overhead Profit	22,253.11 2,225.42 2,225.42
Cleaning Sales Tax	198.42
Replacement Cost Value Net Claim	\$26,902.37 \$26,902.37

Randy Crow



Stonegate Construction & Restoration, LLC

5303 N McColl McAllen, TX 78504 956- 992-8747

1 1-1904 Taxco Dr. Date Taken 2/11/2015

Brownsville, TX 78521.



 2-Roof: Date:Taken: 2/11/2015

Roof.



Stonegate Construction & Restoration, LLC

5303 N. McColl McAllen, TX 78504 956- 992-8747

3 3-Roof Date Taken: 2/11/2015

Roof.



4 4-Roof Date Taken: 2/11/2015

Roof.




0 40 42 0 1 S 2/19/2015 Page: 10

Stonegate Construction & Restoration, LLC

5303 N McColl McAllen, TX 78504 956- 992-8747

5 5-Roof Date Taken 2/11/2015

Roof.



6 6-Roof Date Taken: 2/11/2015

Roof.



Stone ate Stonegate Construction & Restoration, LLC

5303 N. McColl McAllen, TX 78504 956- 992-8747

7 7-Roof

Date Taken: 2/11/2015

Roof.



8 8-Roof Date Taken: 2/11/2015

Roof



Stonegate Construction & Restoration, LLC

5303 N McColl McAllen, TX 78504 956- 992-8747

9 9-Roof Date Taken 2/11/2015

Roof



10 10=Roof: Date-Taken: 2/11/2015

Röse



2015-02-19-1534

2/19/2015

Page 13

Stone atc Stonegate Construction & Restoration, LLC

5303 N McColl McAllen, TX 78504 956- 992-8747

11 11-Roof

Date Taken: 2/11/2015

Roof.



12 12-Roof Date Taken: 2/11/2015

Roof.



Stonegate Construction & Restoration, LLC

5303 N McColl McAllen, TX 78504 956- 992-8747

13 13-Roof Date Taken: 2/11/2015

Roof



14 14-Roof Date Taken: 2/11/2015

Roof.



2015-02-19-1534

2/19/2015


Page 15

Stonegate Construction & Restoration, LLC

5303 N. McColl McAllen, TX 78504 956- 992-8747

15 15-Roof Date Taken: 2/11/2015

Roof



16 16-Roof Date Taken: 2/11/2015

Roof.



Stonegate Construction & Restoration, LLC

5303 N McColl McAllen, TX 78504 956- 992-8747


17 17-Roof Date Taken 2/11/2015

Roof



18 18-Roof: Date:Taken: 2/11/2015

Roof.



2015-02-19-1534

Stonegate Construction & Restoration, LLC

5303 N McColl McAllen, TX 78504 956- 992-8747

19 19-Roof

Date Taken: 2/11/2015

Roof.



20 20-Exterior

Date Taken: 2/11/2015

Right elevation window.



9 4 9 4 2 0 1 6 2/19/2015 Page: 18

Stonegate Construction & Restoration, LLC

5303 N McColl McAllen, TX 78504 956- 992-8747

21 21-Exterior Date Taken: 2/11/2015

Right elevation window.



22 22-Exterior Date Taken: 2/11/2015

Left elevation window.



Stonegate Construction & Restoration, LLC

5303 N. McColl McAllen, TX 78504 956-992-8747

23 23-Exterior

Date Taken: 2/11/2015


Left elevation window.



24 24-Kitchen

Date Taken: 2/11/2015

Kitchen.



04042016 2/19/2015 Page: 20

2015-02-19-1534

StoneSate

Stonegate Construction & Restoration, LLC

5303 N. McColl McAllen, TX 78504 956- 992-8747

25 25-Kitchen Date Taken: 2/11/2015

Kitchen.



26 26-Bathroom Date Taken: 2/11/2015

Bathroom.



Stone

Stonegate Construction & Restoration, LLC

5303 N McColl McAllen, TX 78504 956- 992-8747

27 27-Bathroom Date Taken: 2/11/2015

Bathroom.

